

Response to Request for Information

Reference FOI 002450
Date 26 June 2018

Road Inspection Reports

Request:

I request copies of the road inspection reports for ring road St. Peter's area of Wolverhampton. At the cross roads with Waterloo road. I would require from January to June this year.

[In response to your above request, please find attached information relating to the period 1 January 2018 to 30 June 2018.](#)

Effective: 01/01/2018 to 30/06/2018

Asset Number: 999.00 to 999.00

Display Action Officer: Yes

Site: RING ROAD (44842480)

Site: RING ROAD (44842480)

Locality: WOLVERHAMPTON, WOLVERHAMPTON, WOLVERHAMPTON

Area: No Code Allocated

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset:	999.00	Asset - Locn.:	44842480 - RING ROAD - WHOLE SITE	Feature Type:	Whole Site Feature		Area:	City Centre	
Batch:	114085 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670983	Clay deteriorated around gully	25/06/2018	Near lamp col	H:Cway Deteriorated Surround	Internal		Uncommitted	396943	
Batch:	114083 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670982	Clay deter'n surrounding	25/06/2018	Under glass bridge	H:Cway Deteriorated Surround	Internal		Uncommitted	396942	
Batch:	114081 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670981	Clay broken out adj gully + blocked gully	25/06/2018	Bus lane under railway drive bridge	H:Cway Deteriorated Surround	Internal		Uncommitted	396941	
Batch:	114075 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670978	Deter surround gully	25/06/2018	Near lc108 retain wall side	H:Cway Deteriorated Surround	Internal		Uncommitted	396939	
Batch:	114074 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670976	Deterioration surrounding manhole cover in anti skid	25/06/2018	In junc contra flow bus lane	H:Cway Deteriorated Surround	Internal		Uncommitted	396935	
Batch:	114071 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670975	Block gully	25/06/2018	Stop line contra bus lane	H:Gully Blockage	Internal		Uncommitted	396933	
Batch:	114068 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Linda Saxon2	Date:	25/06/2018
670972	Manhole cover sunken	25/06/2018	Contra flow bus lane o/s Chubb building	H:Manhole Damaged	Internal		Uncommitted	396930	
Batch:	113276 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	16/06/2018
670430	Fill potholes	16/06/2018	Broad st to Stafford st	H:Carriageway Pothole	Internal		Uncommitted	396427	
Batch:	111853 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	31/05/2018
669422	Reinstate cw potholes in right hand lane	31/05/2018	Between Darlington st and salop st	H:Carriageway Pothole	Internal		Uncommitted	395618	
Batch:	110651 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	18/05/2018
668803	Reinstate cw potholes	18/05/2018	Broad st to Stafford st	H:Carriageway Pothole	Internal		Uncommitted	395066	
Batch:	110372 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	16/05/2018
668548	Overlay uneven cw	16/05/2018	Jct Stafford rd	H:Carriageway Pothole	Internal		Uncommitted	394812	
Batch:	109340 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Responsive Maintenance Team 2	Date:	30/04/2018
667662	potholes	30/04/2018	o/s BMW jct birmingham rd, Stafford st jct, Waterloo rd junction	H:Carriageway Pothole	Internal		Uncommitted	394107	
Batch:	109100 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	27/04/2018
667398	Reinstate cw potholes	27/04/2018	Jct Stafford street and Waterloo rd	H:Carriageway Pothole	Internal		Uncommitted	393996	
Batch:	108586 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	John Keates	Date:	23/04/2018
666844	3 FLAG TRIPS	23/04/2018	SLIP ROAD TO STAFFORD STREET NB OS ART COLLEGE CLOSE TO PDX	H:Footway Uneven	Internal		Uncommitted	393707	
Batch:	107098 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Dave Onions	Date:	06/04/2018
665597	Fill pothole on roundabout	06/04/2018	Jct midle cross	H:Carriageway Pothole	Internal		Uncommitted	392738	
Batch:	106645 - Inspection Batch			Route:	Ad-hoc Safety Inspection	Officer:	Responsive Maintenance Team 3	Date:	30/03/2018
665345		30/03/2018		H:Carriageway Pothole	Internal		Uncommitted	392515	

Effective: 01/01/2018 to 30/06/2018

Asset Number: 999.00 to 999.00

Display Action Officer: Yes

Site: RING ROAD (44842480)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	999.00	Asset - Locn.: 44842480 - RING ROAD - WHOLE SITE		Feature Type: Whole Site Feature		Area: City Centre		
Batch:	104689 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 11/02/2018
663343	Fill potholes	11/02/2018	Waterloo rd and Stafford st junctions	H:Carriageway Pothole	Internal		Uncommitted	390928
Batch:	103485 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 07/02/2018
661774	Fill potholes	07/02/2018	Os benhams	H:Carriageway Pothole	Internal		Uncommitted	389584
Batch:	103325 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 06/02/2018
661529	Fill cw pothole	06/02/2018	Left turn from broad street inbound left Hand lane	H:Carriageway Pothole	Internal		Uncommitted	389397
Batch:	102791 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 30/01/2018
660704	Fill pothole left hand lane	30/01/2018	Left turn from bilston rd towards Birmingham rd	H:Carriageway Pothole	Internal		Uncommitted	388677
Batch:	102765 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 30/01/2018
660666	H Carriageway Pothole - CAS-324218 Email Received: 24/01/2018:	30/01/2018	Ring Road,Wolverhampton,WEST MIDLANDS	H:Carriageway Pothole	Internal		Uncommitted	388638
	On the ring road approaching from Wednesfield, there is a sizeable pothole just after the lights as you turn left onto the ringroad just past canal (Enquiry 50215)							
	Fill pothole left hand side							
Batch:	102584 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 26/01/2018
660361	Fill potholes	26/01/2018	Bilston rd to penn rd	H:Carriageway Pothole	Internal		Uncommitted	388351
Batch:	102583 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 26/01/2018
660360	Overlay sunken cover	26/01/2018	Side of kwik fit	H:Carriageway Depression	Internal		Uncommitted	388350
Batch:	101867 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 17/01/2018
659197	Fill potholes around roundabout	17/01/2018	Bilston rd roundabout	H:Carriageway Pothole	Internal		Uncommitted	387459
Batch:	101865 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 17/01/2018
659194	Reset kerb	17/01/2018	Bilston st slip rd	H:Kerb Loose	Internal		Uncommitted	387456
Batch:	100972 - Inspection Batch			Route: Ad-hoc Safety Inspection	Officer:	Dave Onions		Date: 05/01/2018
657727	Fill pothole on joint	05/01/2018	Entrance to bus station	H:Carriageway Pothole	Internal		Uncommitted	386217

Inspection Type(s)					
H Highway Driven Safe Inspect					
H Monthly Safety Inspection					
Site: RING ROAD (44842480)			Area: City Centre		
Asset No: 10,007.00		Asset Id - Location RING ROAD ST ANDREWS - NB RBT CHAPEL ASH - WATER			
Feature Type: H:Highway Section		Contract Area: Highways			
Inspection	Date	Route	Type	Officer	
109312	30/04/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
108572	23/04/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
105350	08/03/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101569	12/01/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
101321	10/01/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
Defect Details					
Defect	Description	Log Date	Location	Organise./Job	Priority
667621		30/04/2018			
666831		23/04/2018	JCT WATERLOO ROAD	393693	H:Cat 2 Med (90 Working Days)
666830	FLAG/FLAG ANKLE TWISTER	23/04/2018	OS LAMP 525 (OS TRAVEL LODGE)	393692	H:Cat 1B (24 hour)
666829	ANKLE TWISTER	23/04/2018	HALF WAY BETWEEN BATH AVENUE STEPS AND TRAVEL LODGE	393691	H:Cat 1B (24 hour)
666828	FLAG/FLAG ANKLE TWISTER	23/04/2018	10M FROM LAMP 517 OS BATHS	393690	H:Cat 1B (24 hour)
666827	WALL FAILING	23/04/2018	OS BREWERY BY TREE ADJACENT TO FOOTWAY	393689	H:Cat 2 Low (180 Working Days)
664092		08/03/2018			
664091		08/03/2018			
658682	4M SCABBING	12/01/2018	CENTRE LINE AT JCT WITH WATERLOO ROAD	387003	H:Cat 2 Low (180 Working Days)
658680	FLAG CRACKED AND ROCKING	12/01/2018	5M FROM LAMP 525	387001	H:Cat 2 Low (180 Working Days)
658679	FLAG/FLAG TRIP	12/01/2018	5M FROM LAMP 523 BY CTV BOX	387000	H:Cat 2 High (30 Working Days)
658677	PAIR OF POSTS	12/01/2018	OPP LAMP 521	386999	H:Cat 2 Low (180 Working Days)
658676	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	9M FROM LAMP 521	386998	H:Cat 2 Low (180 Working Days)
658672	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	8M FROM LAMP 517 (LEVEL WITH TURN LEFT WHITE ARROW)	386994	H:Cat 2 High (30 Working Days)
658671	FLAG/FLAG TRIP	12/01/2018	10M FROM LAMP 515 BY GAS BOX	386993	H:Cat 2 High (30 Working Days)
658291		10/01/2018			

Inspection Type(s)					
H Highway Driven Safe Inspect					
H Monthly Safety Inspection					
Site: RING ROAD (44842480)			Area: City Centre		
Asset No: 10,008.00		Asset Id - Location RING ROAD ST ANDREWS - SB WATERLOO ROAD - RBT C			
Feature Type: H:Highway Section		Contract Area: Highways			
Inspection	Date	Route	Type	Officer	
109309	30/04/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
108547	23/04/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
105364	08/03/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101331	10/01/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101243	10/01/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
Defect Details					
Defect	Description	Log Date	Location	Organise./Job	Priority
667618		30/04/2018			
666817	COVER MISSING	23/04/2018	JCT CHAPEL ASH ROUNDABOUT OS CROWN HOUSE	393677	H:Cat 1B (24 hour)
666816	FLAG/FLAG TRIP	23/04/2018	HALF WAY BETWEEN LAMPS 504 AND 502 (OS CROWN HOUSE)	393675	H:Cat 1B (24 hour)
666814	FLAG/FLAG TRIP	23/04/2018	8M PAST LAMP 504 (OS CROWN HOUSE)	393673	H:Cat 1B (24 hour)
664107		08/03/2018			
658301		10/01/2018			
658218	FLAG/FLAG TRIP	10/01/2018	15M FROM LAMP 504	386651	H:Cat 1B (24 hour)
658216	FLAG/FLAG TRIP	10/01/2018	7M FROM LAMP 504	386649	H:Cat 1B (24 hour)
658215	2M OF FLAG TRIPS	10/01/2018	OS CROWN HOUSE UNDER LARGE SIGN	386648	H:Cat 1B (24 hour)
658210	NO LEFT TURN: PLATE TWIST AND POST LEANING	10/01/2018	OPP BATH ROAD	386647	H:Cat 2 Low (180 Working Days)
658204	VERTICAL MEMBER UNSECURED AND BENT	10/01/2018	OPP ANNABELS (BANKFIELD HOUSE)	386645	H:Cat 2 Med (90 Working D
658202	BREAK UP AND TRIP ALONG CENTRE LINE	10/01/2018	ON PDX OS LAMP 524	386644	H:Cat 2 High (30 Working D

Inspection Type(s)					
H Highway Driven Safe Inspect					
H Monthly Safety Inspection					
Site: RING ROAD (44842480)		Area: City Centre			
Asset No: 10,009.00		Asset Id - Location RING ROAD ST PETERS - EB WATERLOO ROAD - STAFFOR			
Feature Type: H:Highway Section		Contract Area: Highways			
Inspection	Date	Route	Type	Officer	
109308	30/04/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
108581	23/04/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
105334	08/03/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101576	12/01/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
101322	10/01/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
Defect Details					
Defect	Description	Log Date	Location	Organise./Job	Priority
667617		30/04/2018			
666843		23/04/2018	JCT STAFFORD STREET EB	393706	H:Cat 2 (Monitoring)
666841	FLAG/FLAG TRIP	23/04/2018	7M FROM LAMP 623	393704	H:Cat 1B (24 hour)
666840	FLAG/FLAG TRIP	23/04/2018	OS PATH TO ART COLLEGE BY ADVERTISING SIGN	393703	H:Cat 1B (24 hour)
666837	FLAGS LOW AND TRIP (ANKLE TWISTER)	23/04/2018	12M FROM TOP OF STEPS TO MOLINEUX BY CTV BOX REIN	393700	H:Cat 1B (24 hour)
666836	FLAG/FLAG ANKLE TWISTER	23/04/2018	8M FROM TOP OF RAMP FROM MOLINEUX	393698	H:Cat 1B (24 hour)
666834	FLAG/FLAG ANKLE TWISTER	23/04/2018	OPP LAMP 609	393696	H:Cat 1B (24 hour)
666833		23/04/2018	5M OPP LAMP 605	393695	H:Cat 2 Med (90 Working Days)
666832		23/04/2018	OPP LAMP 603	393694	H:Cat 2 Med (90 Working Days)
664073		08/03/2018			
658706	BITMAC UNEVEN/BREAK UP AND TRIP	12/01/2018	JCT STAFFORD STREET BY F/H	387028	H:Cat 2 Low (180 Working Days)
658705	FLAG/FLAG TRIP	12/01/2018	5M FROM TANGENT TO STAFFORD STREET BY FENCE	387027	H:Cat 1B (24 hour)
658704	TRAFFIC BOX REIN MISSING	12/01/2018	OS SCHOOL OF ART DOOR BY GUARDRAIL	387026	H:Cat 2 High (30 Working Days)
658703	OLD CONCRETE REINSTATEMENT BREAK UP AND TRIP	12/01/2018	5M FROM TOP OF STEPS TO MOLINEUX BY MERCURY BOX	387025	H:Cat 1B (24 hour)
658701	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	LEVEL WITH HALF WAY UP RAMP FROM MOLINEUX	387022	H:Cat 2 Low (180 Working Days)
658700	FLAG (MUDDY) LOW AND TRIP	12/01/2018	7M FROM TOP OF RAMP FROM MOLINEUX	387021	H:Cat 1B (24 hour)
658699	FLAG/FLAG TRIP	12/01/2018	OVER ENTRANCE TO MOLINEUX SUBWAY IN CENTRE OF FOOTWAY	387020	H:Cat 2 High (30 Working Days)
658696	GULLY RAISED BY KERB AND TRIP	12/01/2018	OPP LAMP 611 TO OS LAMP 613	387017	H:Cat 1B (24 hour)
658695	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	OPP LAMP 611	387016	H:Cat 1B (24 hour)
658694	2 FLAG / FLAG TRIPS (SIDEWAYS)	12/01/2018	10M OPP LAMP 609 TOWARDS OPP LAMP 611	387015	H:Cat 2 High (30 Working Days)
658692	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	OPP LAMP 607 TO 609	387013	H:Cat 1B (24 hour)
658690	FLAG RAISED	12/01/2018	OPP LAMP 605	387010	H:Cat 2 Low (180 Working Days)
658689		12/01/2018	OPP LAMP 603	387009	H:Cat 2 Med (90 Working Days)
658687	TACTILE RAISED AND TRIP BY KERB	12/01/2018	PDX OPP DERWENT HOUSE IN CENTRE RESERVATION	387008	H:Cat 1B (24 hour)
658292		10/01/2018			

Inspection Type(s)					
H Highway Driven Safe Inspect					
H Monthly Safety Inspection					
Site: RING ROAD (44842480)			Area: City Centre		
Asset No: 10,010.00		Asset Id - Location RING ROAD ST PETERS - WB STAFFORD STREET - WATER			
Feature Type: H:Highway Section			Contract Area: Highways		
Inspection	Date	Route	Type	Officer	
109307	30/04/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
108414	20/04/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
105367	08/03/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101335	10/01/2018	H:Monthly Driven Ring Road	H Highway Driven Safe Inspect	Linda Saxon	
101228	10/01/2018	H CITY ROUTE 1	H Monthly Safety Inspection	John Keates	
Defect Details					
Defect	Description	Log Date	Location	Organise./Job	Priority
667616		30/04/2018			
666682	RAISED AND TRIP BY FOOTWAY	20/04/2018	OS RED LION STREET STEPS BY END OF FENCE	393552	H:Cat 1B (24 hour)
666679	MANHOLE LOOSE - MOVEMENT MAKING SURROUND BREAK UP	20/04/2018	OS LAMP 604 IN CARRIAGEWAY	393549	H:Cat 2 Med (90 Working D
666678	2NO FLAG/FLAG TRIPS	20/04/2018	3M PAST LAMP 606	393548	H:Cat 1B (24 hour)
666674	FLAG/FLAG TRIPS	20/04/2018	LEVEL WITH TOP OF MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	393544	H:Cat 1B (24 hour)
666673	BITMAC RAISED BY ROOTS AND DAMAGED	20/04/2018	BEHIND MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	393543	H:Cat 1B (24 hour)
666671	VARIOUS FLAG TRIPS	20/04/2018	BEHIND MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	393541	H:Cat 1B (24 hour)
666668	FLAG/FLAG TRIP	20/04/2018	OS LAMP 618 BY END OF GUARDRAIL	393540	H:Cat 1B (24 hour)
666666	BITMAC DEPRESSION ALONG CENTRE LINE AND BREAK UP OVER MANHOLE	20/04/2018	JCT STAFFORD STREET BETWEEN PRAM XINGS	393539	H:Cat 2 High (30 Working D
664110		08/03/2018			
658305		10/01/2018			
658193	FLAG LOW/TRIP BY KERB	10/01/2018	10M PAST LAMP 604	386639	H:Cat 2 High (30 Working D
658190	FLAG LOW/TRIP BY CONCRETE REIN	10/01/2018	OS LAMP 604 BY BT BOX	386636	H:Cat 2 High (30 Working D
658186	CONCRETE REIN BREAK UP AND TRIP	10/01/2018	JCT NORTH STREET BY TWIN COVER BOX	386633	H:Cat 1B (24 hour)
658185	FLAG/FLAG TRIPS	10/01/2018	LEVEL WITH TOP OF RAMP FROM MOLINEUX TUNNEL	386632	H:Cat 1B (24 hour)
658182	60M OF UNEVEN FLAGS AND TRIPS	10/01/2018	BEHIND STEPS/RAMP TO MOLINEUX TUNNEL	386631	H:Cat 2 Low (180 Working Days)
658181	FLAG/FLAG TRIP	10/01/2018	10M FROM TOP OF SUBWAY RAMP TO NORTH STREET	386630	H:Cat 1B (24 hour)
658180	FLAG/FLAG TRIP	10/01/2018	BEHIND MOLINEUX TUNNEL- 1 FLAG FROM BITMAC PATCH	386629	H:Cat 2 High (30 Working D
658179	BITMAC RAISED AND BREAK UP BY ROOTS	10/01/2018	LEVEL WITH TOP OF STEPS FROM MOLINEUX SUBWAY	386628	H:Cat 1B (24 hour)
658178	2M LONG DEPRESSION ALONG CENTRE LINE	10/01/2018	20M FROM STAFFORD STREET SOUTH BOUND	386627	H:Cat 2 Med (90 Working D

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,007.00

Asset Id - Location: RING ROAD ST ANDREWS - NB RBT CHAPEL ASH - WATER

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 109312 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 30/04/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	

Defect No.	Description	Log Date	Location	Type	Organisation	Status
667621		30/04/2018		NONE		Unactioned

Batch: 108572 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 23/04/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	

Defect No.	Description	Log Date	Location	Type	Organisation	Status
666831		23/04/2018	JCT WATERLOO ROAD	CWDA		Uncommitted
666830	FLAG/FLAG ANKLE TWISTER	23/04/2018	OS LAMP 525 (OS TRAVEL LODGE)	FWUN		Uncommitted
666829	ANKLE TWISTER	23/04/2018	HALF WAY BETWEEN BATH AVENUE STEPS AND TRAVEL LODGE	FWUN		Uncommitted
666828	FLAG/FLAG ANKLE TWISTER	23/04/2018	10M FROM LAMP 517 OS BATHS	FWUN		Uncommitted
666827	WALL FAILING	23/04/2018	OS BREWERY BY TREE ADJACENT TO FOOTWAY	HSDA		Uncommitted

Batch: 105350 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 08/03/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	

Defect No.	Description	Log Date	Location	Type	Organisation	Status
664092		08/03/2018		NONE		Unactioned
664091		08/03/2018		NONE		Unactioned

Batch: 101569 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 12/01/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	5569/5631/5577/5625/5627/5628/5629/5630/5568/11524/11527/11529/8967/11533/5630/8968/16330/5568/8964/8966/17488 - THE CENTRE RES HAS FOOTWAY STRUCTURALLY UNSOUND

Defect No.	Description	Log Date	Location	Type	Organisation	Status
658682	4M SCABBING	12/01/2018	CENTRE LINE AT JCT WITH WATERLOO ROAD	CWDA		Uncommitted
658680	FLAG CRACKED AND ROCKING	12/01/2018	5M FROM LAMP 525	FWDA		Uncommitted
658679	FLAG/FLAG TRIP	12/01/2018	5M FROM LAMP 523 BY CTV BOX	FWUN		Uncommitted
658677	PAIR OF POSTS	12/01/2018	OPP LAMP 521	SGNP		Uncommitted
658676	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	9M FROM LAMP 521	FWUN		Uncommitted
658672	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	8M FROM LAMP 517 (LEVEL WITH TURN LEFT WHITE ARROW)	FWUN		Uncommitted
658671	FLAG/FLAG TRIP	12/01/2018	10M FROM LAMP 515 BY GAS BOX	FWUN		Uncommitted

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,007.00

Asset Id - Location: RING ROAD ST ANDREWS - NB RBT CHAPEL ASH - WATER

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 101321 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	5569/5631/5577/5625/5627/5628/5629/5630/ 5568/11524/11527/11529/8967/11533/5630/ 8968/16330/5568/8964/8966/17488 - THE CENTRE RES HAS FOOTWAY STRUCTURALLY UNSOUND

Defect No.	Description	Log Date	Location	Type	Organisation	Status
658291		10/01/2018		NONE		Unactioned

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,008.00

Asset Id - Location: RING ROAD ST ANDREWS - SB WATERLOO ROAD - RBT CH

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 109309 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 30/04/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	As New	1.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	4992/6568/8972/8971/11541		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
667618		30/04/2018		NONE		Unactioned

Batch: 108547 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 23/04/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	As New	1.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	4992/6568/8972/8971/11541		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
666817	COVER MISSING	23/04/2018	JCT CHAPEL ASH ROUNDABOUT OS CROWN HOUSE	GYMI		Uncommitted
666816	FLAG/FLAG TRIP	23/04/2018	HALF WAY BETWEEN LAMPS 504 AND 502 (OS CROWN HOUSE)	FWUN		Uncommitted
666814	FLAG/FLAG TRIP	23/04/2018	8M PAST LAMP 504 (OS CROWN HOUSE)	FWUN		Uncommitted

Batch: 105364 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 08/03/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	As New	1.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	4992/6568/8972/8971/11541		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
664107		08/03/2018		NONE		Unactioned

Batch: 101331 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	As New	1.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	4992/6568/8972/8971/11541		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
658301		10/01/2018		NONE		Unactioned

Batch: 101243 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	As New	1.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	4992/6568/8972/8971/11541		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
658218	FLAG/FLAG TRIP	10/01/2018	15M FROM LAMP 504	FWUN		Uncommitted
658216	FLAG/FLAG TRIP	10/01/2018	7M FROM LAMP 504	FWUN		Uncommitted
658215	2M OF FLAG TRIPS	10/01/2018	OS CROWN HOUSE UNDER LARGE SIGN	FWUN		Uncommitted
658210	NO LEFT TURN: PLATE TWIST AND POST LEANING	10/01/2018	OPP BATH ROAD	SGDI		Uncommitted
658204	VERTICAL MEMBER UNSECURED AND BENT	10/01/2018	OPP ANNABELS (BANKFIELD HOUSE)	PRDA		Uncommitted
658202	BREAK UP AND TRIP ALONG CENTRE LINE	10/01/2018	ON PDX OS LAMP 524	CWPH		Uncommitted

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,009.00

Asset Id - Location: RING ROAD ST PETERS - EB WATERLOO ROAD - STAFFOR

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 109308 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 30/04/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Structurally Impaired	4.0000	6265/10757/6262/6265/6269/10392/6260/16340/16341/10757/10392

Defect No.	Description	Log Date	Location	Type	Organisation	Status
667617		30/04/2018		NONE		Unactioned

Batch: 108581 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 23/04/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Structurally Impaired	4.0000	6265/10757/6262/6265/6269/10392/6260/16340/16341/10757/10392

Defect No.	Description	Log Date	Location	Type	Organisation	Status
666843		23/04/2018	JCT STAFFORD STREET EB	CWPH		Uncommitted
666841	FLAG/FLAG TRIP	23/04/2018	7M FROM LAMP 623	FWUN		Uncommitted
666840	FLAG/FLAG TRIP	23/04/2018	OS PATH TO ART COLLEGE BY ADVERTISING SIGN	FWUN		Uncommitted
666837	FLAGS LOW AND TRIP (ANKLE TWISTER)	23/04/2018	12M FROM TOP OF STEPS TO MOLINEUX BY CTV BOX REIN	FWUN		Uncommitted
666836	FLAG/FLAG ANKLE TWISTER	23/04/2018	8M FROM TOP OF RAMP FROM MOLINEUX	FWUN		Uncommitted
666834	FLAG/FLAG ANKLE TWISTER	23/04/2018	OPP LAMP 609	FWUN		Uncommitted
666833		23/04/2018	5M OPP LAMP 605	GYBL		Uncommitted
666832		23/04/2018	OPP LAMP 603	GYBL		Uncommitted

Batch: 105334 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 08/03/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	6265/10757/6262/6265/6269/10392/6260/16340/16341/10757/10392

Defect No.	Description	Log Date	Location	Type	Organisation	Status
664073		08/03/2018		NONE		Unactioned

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,009.00

Asset Id - Location: RING ROAD ST PETERS - EB WATERLOO ROAD - STAFFOF

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 101576 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 12/01/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	6265/10757/6262/6265/6269/10392/6260/16340/16341/10757/10392

Defect No.	Description	Log Date	Location	Type	Organisation	Status
658706	BITMAC UNEVEN/BREAK UP AND TRIP	12/01/2018	JCT STAFFORD STREET BY F/H	FWDS		Uncommitted
658705	FLAG/FLAG TRIP	12/01/2018	5M FROM TANGENT TO STAFFORD STREET BY FENCE	FWUN		Uncommitted
658704	TRAFFIC BOX REIN MISSING	12/01/2018	OS SCHOOL OF ART DOOR BY GUARDRAIL	FWDS		Uncommitted
658703	OLD CONCRETE REINSTATEMENT BREAK UP AND TRIP	12/01/2018	5M FROM TOP OF STEPS TO MOLINEUX BY MERCURY BOX	FWDA		Uncommitted
658701	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	LEVEL WITH HALF WAY UP RAMP FROM MOLINEUX	FWUN		Uncommitted
658700	FLAG (MUDDY) LOW AND TRIP	12/01/2018	7M FROM TOP OF RAMP FROM MOLINEUX	FWUN		Uncommitted
658699	FLAG/FLAG TRIP	12/01/2018	OVER ENTRANCE TO MOLINEUX SUBWAY IN CENTRE OF FOOTWAY	FWUN		Uncommitted
658696	GULLY RAISED BY KERB AND TRIP	12/01/2018	OPP LAMP 611 TO OS LAMP 613	GYDI		Uncommitted
658695	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	OPP LAMP 611	FWUN		Uncommitted
658694	2 FLAG / FLAG TRIPS (SIDEWAYS)	12/01/2018	10M OPP LAMP 609 TOWARDS OPP LAMP 611	FWUN		Uncommitted
658692	FLAG/FLAG TRIP (SIDEWAYS)	12/01/2018	OPP LAMP 607 TO 609	FWUN		Uncommitted
658690	FLAG RAISED	12/01/2018	OPP LAMP 605	FWUN		Uncommitted
658689		12/01/2018	OPP LAMP 603	GYBL		Uncommitted
658687	TACTILE RAISED AND TRIP BY KERB	12/01/2018	PDX OPP DERWENT HOUSE IN CENTRE RESERVATION	FWUN		Uncommitted

Batch: 101322 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Structurally Impaired	4.0000	6265/10757/6262/6265/6269/10392/6260/16340/16341/10757/10392

Defect No.	Description	Log Date	Location	Type	Organisation	Status
658292		10/01/2018		NONE		Unactioned

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,010.00

Asset Id - Location: RING ROAD ST PETERS - WB STAFFORD STREET - WATER

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 109307 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 30/04/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000			
H:Footway Network Survey	FNS	Aesthetically Impaired	2.0000	6547/6557/6559/6561/12724		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
667616		30/04/2018		NONE		Unactioned

Batch: 108414 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 20/04/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000			
H:Footway Network Survey	FNS	Aesthetically Impaired	2.0000	6547/6557/6559/6561/12724		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
666682	RAISED AND TRIP BY FOOTWAY	20/04/2018	OS RED LION STREET STEPS BY KBDI END OF FENCE			Uncommitted
666679	MANHOLE LOOSE - MOVEMENT MAKING SURROUND BREAK UP	20/04/2018	OS LAMP 604 IN CARRIAGEWAY	CWDS		Uncommitted
666678	2NO FLAG/FLAG TRIPS	20/04/2018	3M PAST LAMP 606	FWUN		Uncommitted
666674	FLAG/FLAG TRIPS	20/04/2018	LEVEL WITH TOP OF MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	FWUN		Uncommitted
666673	BITMAC RAISED BY ROOTS AND DAMAGED	20/04/2018	BEHIND MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	FWDA		Uncommitted
666671	VARIOUS FLAG TRIPS	20/04/2018	BEHIND MOLINEUX SUBWAY RAMP (SIDE OPP FOOTBALL GROUND)	FWUN		Uncommitted
666668	FLAG/FLAG TRIP	20/04/2018	OS LAMP 618 BY END OF GUARDRAIL	FWUN		Uncommitted
666666	BITMAC DEPRESSION ALONG CENTRE LINE AND BREAK UP OVER MANHOLE	20/04/2018	JCT STAFFORD STREET BETWEEN PRAM XINGS	CWDA		Uncommitted

Batch: 105367 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 08/03/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	6547/6557/6559/6561/12724		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
664110		08/03/2018		NONE		Unactioned

Batch: 101335 - Inspection Batch

Route: H:Monthly Driven Ring Road

Officer: Linda Saxon

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes		
H:Carriageway Network Survey	CNS	Aesthetically Impaired	2.0000			
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	6547/6557/6559/6561/12724		
Defect No.	Description	Log Date	Location	Type	Organisation	Status
658305		10/01/2018		NONE		Unactioned

Inspected: 01/01/2018 to 30/06/2018

Site: RING ROAD (44842480)

Asset Number: 10007.00 to 10010.00

Report Type: Assessment

Site: RING ROAD (44842480)

Area: City Centre

Asset No: 10,010.00

Asset Id - Location: RING ROAD ST PETERS - WB STAFFORD STREET - WATER

Feature Type: H:Highway Section

Contract Area: Highways

Batch: 101228 - Inspection Batch

Route: H CITY ROUTE 1

Officer: John Keates

Date: 10/01/2018

Observation Type	Code	Grade	Score	Notes
H:Carriageway Network Survey	CNS	As New	1.0000	
H:Footway Network Survey	FNS	Functionally Impaired	3.0000	6547/6557/6559/6561/12724

Defect No.	Description	Log Date	Location	Type	Organisation	Status
658193	FLAG LOW/TRIP BY KERB	10/01/2018	10M PAST LAMP 604	FWUN		Uncommitted
658190	FLAG LOW/TRIP BY CONCRETE REIN	10/01/2018	OS LAMP 604 BY BT BOX	FWUN		Uncommitted
658186	CONCRETE REIN BREAK UP AND TRIP	10/01/2018	JCT NORTH STREET BY TWIN COVER BOX	FWDS		Uncommitted
658185	FLAG/FLAG TRIPS	10/01/2018	LEVEL WITH TOP OF RAMP FROM MOLINEUX TUNNEL	FWUN		Uncommitted
658182	60M OF UNEVEN FLAGS AND TRIPS	10/01/2018	BEHIND STEPS/RAMP TO MOLINEUX TUNNEL	FWUN		Uncommitted
658181	FLAG/FLAG TRIP	10/01/2018	10M FROM TOP OF SUBWAY RAMP TO NORTH STREET	FWUN		Uncommitted
658180	FLAG/FLAG TRIP	10/01/2018	BEHIND MOLINEUX TUNNEL- 1 FLAG FROM BITMAC PATCH	FWUN		Uncommitted
658179	BITMAC RAISED AND BREAK UP BY ROOTS	10/01/2018	LEVEL WITH TOP OF STEPS FROM MOLINEUX SUBWAY	FWDA		Uncommitted
658178	2M LONG DEPRESSION ALONG CENTRE LINE	10/01/2018	20M FROM STAFFORD STREET SOUTH BOUND	CWDE		Uncommitted